



The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE Lieutenant Governor

Representatives Present During the Inspection: Company lan McClain Associate Engineer

Karl Houskeeper Environmental Scientist III

# **Inspection Report**

Permit Number:	C0150015
Inspection Type:	PARTIAL
Inspection Date:	Thursday, April 01, 2010
Start Date/Time:	4/1/2010 8:00:00 AM
End Date/Time:	4/1/2010 1:00:00 PM
Last Inspection:	Tuesday, March 16, 2010

Inspector: Karl Houskeeper, Environmental Scientist III

Weather: Overcast, Temp. 33 Deg. F. InspectionID Report Number: 2318

**Types of Operations** 

Accepted by: jhelfric

4/26/2010

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO SESSER OPERATIONS

Site: EMERY DEEP MINE

Address: PO BOX 566, SESSER IL 62884

County: EMERY

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

#### **Current Acreages**

442.50	<b>Total Permitted</b>		
248.50	<b>Total Disturbed</b>		
	Phase I		
	Phase II		
	Phase III		

Min	eral	Own	ers	hi	D

✓ Underground **✓** Federal State Surface County Loadout Fee Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Inspector's Signature:

Date

Thursday, April 01, 2010

Karl Houskeeper, Environmental Scientist III

Inspector ID Number: 49

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.



Permit Number: C0150015
Inspection Type: PARTIAL

Inspection Date: Thursday, April 01, 2010

Page 2 of 3

#### REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
  - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
  - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale				
2.	Signs and Markers	✓		~	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	<b>V</b>		<b>✓</b>	
4.b	Hydrologic Balance: Sediment Ponds and Impoundments				
4.c	Hydrologic Balance: Other Sediment Control Measures				
4.d	Hydrologic Balance: Water Monitoring				
4.e	Hydrologic Balance: Effluent Limitations				
5.	Explosives				
6.	Disposal of Excess Spoil, Fills, Benches				
7.	Coal Mine Waste, Refuse Piles, Impoundments				
8.	Noncoal Waste	<b>✓</b>		<b>✓</b>	
9.	Protection of Fish, Wildlife and Related Environmental Issues				
10.	Slides and Other Damage				
11.	Contemporaneous Reclamation				
12.	Backfilling And Grading				
13.	Revegetation				
14.	Subsidence Control				
15.	Cessation of Operations				
16.a	Roads: Construction, Maintenance, Surfacing				
16.b	Roads: Drainage Controls				
17.	Other Transportation Facilities				
18.	Support Facilities, Utility Installations				
19.	AVS Check				
20.	Air Quality Permit				
21.	Bonding and Insurance				
22.	Other				

Permit Number: C0150015
Inspection Type: PARTIAL

Inspection Date: Thursday, April 01, 2010

Page 3 of 3

### 2. Signs and Markers

The mine identification signs at the main facility and 4th east portal area are both located at the point of public access to the permit area and contain the required information.

# 4.a Hydrologic Balance: Diversions

Belting is in the diversion by the portal access road. The belting needs to be removed.

## 8. Noncoal Waste

Garbage cans have been placed throughout the main parking lot. Main parking lot is free of noncoal waste items. The area shows a marked improvement from the two previous inspections.